



Atlas Inspection Technologies Case Study

Case Study: Valve Seat Inspection

Company: Large Tanker Fleet

Location: CA

Scope of Project: Inspecting 12 cylinders valve seats through injectors

Key Points:

- Project completed with no safety or environmental issues
- Completed on time and on budget
- Project required 1 inspector

Special Considerations/Challenges:

- Required full articulation cameras
- No problems found other than slight marring on cylinder walls to be watched during future inspections

Equipment Used: 8mm ITC itools

Lead Technician: Curt Harke
Direct: 951.252.2909
Mobile: 760.814.5544
Email: curt@atlas-inspection.com

Atlas Inspection Technologies, Inc. 800.281.0650 Toll Free
500 Elliott Avenue West, Suite A 206.774.8704 Local and Intl'
Seattle, WA 98119 USA 206.792.7000 Fax

Rentals • Repairs • Sales • Field Inspections USA • Canada • Europe

www.atlas-inspection.com